

2013 S09 IP68 téléphone mobile étanche android 4.2 téléphone quad core

Pourquoi devriez-vous acheter ce téléphone?

Populaire S09 IP68 étanche téléphone

Écran 4,3 pouces, Android 4.2 MTK6589 quad core
GSM850 / 1900/900/1800, WCDMA 850/1900/2100
NFC + Talkie-walkie

Remarque:

Débloqué pour le monde entier, Ce téléphone intelligent robuste fonctionne sur les fréquences du réseau GSM 850/900/1800/1900 MHz et WCDMA / HSPA 850/1900 / 2100MHz.

Confirmer avec vos transporteurs ou fournisseurs avant d'acheter cet article. Pour vérifier la fréquence de réseau spécifique pour votre opérateur et votre région.

Spécification

(Unlocked modèle, conçu pour les personnes qui vivent et travaille dans la nature, comme la police, Soldat, athlète, voyageurs extérieure, les travailleurs souterrains, site de construction ... etc, très populaire chez les personnes qui sont pratiquer des sports de plein air, en particulier dans l'UE et en Amérique du Nord .)

Structure	
Modèle	BS-S09
Niveau IP	IP68 étanche à la poussière et
Clés	Vol +/- Réinitialiser la maison d'alimentation PTT
Antenne	GSM WCDMA GPS BT FM
Batterie	2800mAh
Haut-parleur	Un haut-parleur
Torche LED	Oui
Lampe de poche	Oui
Dual SIM	Oui
	3,5 mm pour écouteurs
Connexion Plug-	Chargeur USB
	USB2.0
Taille (L * W * H) & amp; Poids	145,5 * 73 * 20.8MM / 256g (avec batterie)
Matériel	
Chipset	MTK6589W (quad core 1.2G)
Fréquence	GSM / GPRS / EDGE 850/900/1800/1900
	WCDMA / HSPA 850/1900/2100
Mémoire	RAM 1 Go + 4 Go ROM
Mémoire flash	Max.Support 32G
Exposition	Écran: 4,3 "QHD
	Résolution: 960 x 540
	Caméra frontale: 0,3
Caméra	Caméra arrière: 8,0 M (avec lampe de poche, Auto Focus)
	Lampe de poche: Oui
	Vidéo: Oui
Le chat de la vidéo	Oui
Capteur	G-sensor, capteur de lumière, gyroscope, capteur de distance
BT	BT 2.1
FM	Oui
GPS	Oui
Wifi	IEEE 802.11b / g / n

NFC	En option
Talkie-walkie	En option
Logiciel	
OS	Android 4.2
Langue	Multi-Langues
Saisie	Saisie intelligente
Message	SMS, MMS
Email	Records SMS: 1000
Répertoire	Oui
	Records: 1000
	Groupe: 5
	Format audio: MP3, WAV, OGG, AMR, MIDI, AAC
	Format vidéo: 3GP, MPEG4,
Multi-Médias	Photo Vue: Zoom Out / In, Photo Rotation / Switch
	Enregistrement
Sonnerie	Audio & Vidéo Jouer Jouer Background
Outils privées	64 Chord / MP3 / MIDI / AMR / WAV / AAC
Sécurité	Calculatrice Calendrier Jeu alarme Mémo
Power On Animations	Appel de verrouillage Verrouillage du clavier touche latérale Loc Histoire de verrouillage
Arrêt Animations	Oui
Accessoire	Oui
Batterie	1
Chargeur	1
Écouteur	1
Câble USB	1
Hang-Out trou	Oui
Certificat	
ROHS CE	Oui

REMARQUE: Pour assurer étanche, Se il vous plaît assurez-vous que la prise du casque, USB connecter et couvercle de la batterie cloesd correctement. merci





Verification of Compliance

This device is in conformity with Part 15 of the FCC Rules and Regulations for Information Technology Equipment. Operation of this product is subject to the following two conditions:
(1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

Responsible Party : Best Source International Limited
Address : 28F, 68Room, Seg Plaza, North Rd., Huaqiang, Shenzhen, Guangdong, China

EUT Certification Summary
Equipment Class : FCC Part 15 Subpart B Class B
Report Number : ATE20042728
Tested by : Accurate Technology Co., Ltd.

We, the responsible party:
Best Source International Limited
Declare that the product
Charger
Model No.: AP, DP



APPROVED
Martin
(Manager)

Date: December 25, 2006

was tested to conform to the applicable FCC Rules and Regulations. The method of testing was in accordance to the most accurate measurement standards possible, and that all necessary steps have been taken to ensure that all production units of the same equipment will continue to comply with the Federal Communications Commission's requirements.

Certificate of Registration



The Governing Board of
Q.A. International Certification Limited
hereby grants to:

Best Source International Ltd.
Registration No.: QAC / CN / 10095 - A

hereinafter called the Registered Company the right to be listed in the Directory of Registered Companies in respect of the services listed below. These services shall be offered to the Registered Company or at from only the address given below in accordance with the quality management system in compliance with ISO 9001:2005.

Address to which this Certificate refers:

No.3, Shuangnan Industrial Park, Gaohe Community, Xixiang Street,
Bao'an District, Shenzhen City, Guangdong Province, P.R. China

Approved Scope to which this Certificate refers:

The Processing of PCB (Printed Circuit Board Assembly) for Computer parts, Tablet PC, Smart Phone, Android TV, Security Control Products and Management of Related Environmental Aspects.

(Further clarification regarding the Scope of this Certificate and the applicability of ISO 9001:2005 requirements may be obtained by consulting the organization)

Signed for and on behalf of the Board:

CHAIRMAN

SCHEME MANAGER

A. J. Duffield

A. Carter

Certificate Issue Date: 10th January 2011 - Certificate Expiry Date: 2nd February 2014
Date of Initial Registration: 2nd February 2011 - Re-assessment Date: 2nd February 2014

This Certificate of Registration is granted subject to the Regulations approved by the Board.

A INTERNATIONAL

International Certification Ltd.
11 Road
London
United Kingdom



EC-R&TTE Certificate

No.: BST13020193Y-IEC-1

Submitter : GIG ADVANCE TECHNOLOGY & ELECTRONIC CO., LTD.
Manufacturer : 11F, 68Room, Seg Plaza, North Rd., Huaqiang, Shenzhen, Guangdong, China
Product : 8.7inch Tablet PC with WIFI Dual Camera
Model : SP905, RH9750, MT9750

Essential requirement	Applied Specifications/Standards	Documentary Evidence	Result
AN.1.101	EMC	EN 55022	Pass
AN.1.102	EMC	EN 55024	Pass
AN.1.103	EMC	EN 55025	Pass
AN.1.104	EMC	EN 55026	Pass


The EUT described above has been tested by us with the listed standards and found in compliance with the council R&TTE directive 99/5/EC. It is possible to use CE marking to demonstrate the compliance with this Directive.
The scope of evaluation relates to the submitted documents only.



Christina
Manager
March 11, 2013

Shenzhen BST Technology Co., Ltd.

Building No.23-24, Zhongyuan Industrial Park, Guanhu Road, Bao'an District, Shenzhen, Guangdong, China
Tel: 400-882-8828 E-mail: bst@bst.com.cn Complaints hotline: 86-755-26747758 http://www.bst.com.cn



CERTIFICATE OF R&TTE COMPLIANCE

According to Directive: 1999/5/EC
Ref. No.: 2011NT024558B/024558B/024558B/024558B

Product: 7" MID
Applicant: BEST SOURCE INTERNATIONAL CO.,
Address: Shenzhen City, Guangdong Province, China
Manufacturer: BEST SOURCE INTERNATIONAL CO.,
Address: 68Room, Seg Plaza, North Rd., Huaqiang, Shenzhen
Model: A0701, R0702
Rating: Input AC: 100-240V/Output DC: 5V/1.5A

The test sample of product has been tested to the test (standards) to comply with the following standards:

Standard(s):
Article 3.1a) EN 60950-1:2006 EN 62311:2006
Article 3.1b) EN 50148-1 V1.1:2006-04
EN 301 488-1 V2.1.1:2005-05
Article 3.2) EN 300 328 V1.7.1:2006-10

Test report(s) No.:
NTEK-2011NT024558B/024558B/024558B/024558B
NTEK-2011NT024558B/024558B/024558B/024558B
NTEK-2011NT024558B/024558B/024558B/024558B

Based on the voluntary assessment of the product sample and technical file, we confirm that the above-mentioned product meets the requirements of the EC directive.
The CE mark as shown below can be used, under the responsibility of the manufacturer or the importer, after completion of an EC declaration of conformity and compliance with all relevant EC directives.



Approved by (Date):

Martin
(Manager)

NTEK Testing Technology Co., Ltd.
Address: 11F, 68Room, Seg Plaza, North Rd., Huaqiang, Shenzhen, Guangdong, China
Tel: 400-882-8828 E-mail: bst@bst.com.cn Complaints hotline: 86-755-26747758 http://www.bst.com.cn

Certificate of Registration



The Governing Board of
Q.A. International Certification Limited
hereby grants to:

BestSource International Ltd.
Registration No.: QAC / CN / 10092 - A

hereinafter called the Registered Company the right to be listed in the Directory of Registered Companies in respect of the services listed below. These services shall be offered to the Registered Company or at from only the address given below in accordance with the environmental management system in compliance with ISO 14001:2004.

Address to which this Certificate refers:

No.3, Shuangnan Industrial Park, Gaohe Community, Xixiang Street,
Bao'an District, Shenzhen City, Guangdong Province, P.R. China

Approved Scope to which this Certificate refers:

The Processing of PCB (Printed Circuit Board Assembly) for Computer parts, Tablet PC, Smart Phone, Android TV, Security Control Products and Management of Related Environmental Aspects.

Signed for and on behalf of the Board:

CHAIRMAN

SCHEME MANAGER

A. J. Duffield

A. Carter

Certificate Issue Date: 10th January 2011 - Certificate Expiry Date: 2nd February 2014
Date of Initial Registration: 2nd February 2011 - Re-assessment Date: 2nd February 2014

This Certificate of Registration is granted subject to the Regulations approved by the Board.

A INTERNATIONAL

International Certification Ltd.
11 Road
London
United Kingdom



Certificate of Compliance

Certificate Number: BST13020193Y-1RC-4

Applicant : GIG ADVANCE TECHNOLOGY & ELECTRONIC CO., LTD.
Manufacturer : 11F, 68Room, Seg Plaza, North Rd., Huaqiang, Shenzhen, Guangdong, China
Product : 8.7inch Tablet PC with WIFI Dual Camera
Model : SP905, RH9750, MT9750

Test Standard : EPA305B:1996, EN1120:2001, EPA3052:1996, EPA3055A:1996, EPA3055B:1996, EPA3055C:1996, EPA3055D:1996, EPA3055E:1996, EPA3055F:1996, EPA3055G:1996, EPA3055H:1996, EPA3055I:1996, EPA3055J:1996, EPA3055K:1996, EPA3055L:1996, EPA3055M:1996, EPA3055N:1996, EPA3055O:1996, EPA3055P:1996, EPA3055Q:1996, EPA3055R:1996, EPA3055S:1996, EPA3055T:1996, EPA3055U:1996, EPA3055V:1996, EPA3055W:1996, EPA3055X:1996, EPA3055Y:1996, EPA3055Z:1996, EPA3055AA:1996, EPA3055AB:1996, EPA3055AC:1996, EPA3055AD:1996, EPA3055AE:1996, EPA3055AF:1996, EPA3055AG:1996, EPA3055AH:1996, EPA3055AI:1996, EPA3055AJ:1996, EPA3055AK:1996, EPA3055AL:1996, EPA3055AM:1996, EPA3055AN:1996, EPA3055AO:1996, EPA3055AP:1996, EPA3055AQ:1996, EPA3055AR:1996, EPA3055AS:1996, EPA3055AT:1996, EPA3055AU:1996, EPA3055AV:1996, EPA3055AW:1996, EPA3055AX:1996, EPA3055AY:1996, EPA3055AZ:1996, EPA3055BA:1996, EPA3055BB:1996, EPA3055BC:1996, EPA3055BD:1996, EPA3055BE:1996, EPA3055BF:1996, EPA3055BG:1996, EPA3055BH:1996, EPA3055BI:1996, EPA3055BJ:1996, EPA3055BK:1996, EPA3055BL:1996, EPA3055BM:1996, EPA3055BN:1996, EPA3055BO:1996, EPA3055BP:1996, EPA3055BQ:1996, EPA3055BR:1996, EPA3055BS:1996, EPA3055BT:1996, EPA3055BU:1996, EPA3055BV:1996, EPA3055BW:1996, EPA3055BX:1996, EPA3055BY:1996, EPA3055BZ:1996, EPA3055CA:1996, EPA3055CB:1996, EPA3055CC:1996, EPA3055CD:1996, EPA3055CE:1996, EPA3055CF:1996, EPA3055CG:1996, EPA3055CH:1996, EPA3055CI:1996, EPA3055CJ:1996, EPA3055CK:1996, EPA3055CL:1996, EPA3055CM:1996, EPA3055CN:1996, EPA3055CO:1996, EPA3055CP:1996, EPA3055CQ:1996, EPA3055CR:1996, EPA3055CS:1996, EPA3055CT:1996, EPA3055CU:1996, EPA3055CV:1996, EPA3055CW:1996, EPA3055CX:1996, EPA3055CY:1996, EPA3055CZ:1996, EPA3055DA:1996, EPA3055DB:1996, EPA3055DC:1996, EPA3055DD:1996, EPA3055DE:1996, EPA3055DF:1996, EPA3055DG:1996, EPA3055DH:1996, EPA3055DI:1996, EPA3055DJ:1996, EPA3055DK:1996, EPA3055DL:1996, EPA3055DM:1996, EPA3055DN:1996, EPA3055DO:1996, EPA3055DP:1996, EPA3055DQ:1996, EPA3055DR:1996, EPA3055DS:1996, EPA3055DT:1996, EPA3055DU:1996, EPA3055DV:1996, EPA3055DW:1996, EPA3055DX:1996, EPA3055DY:1996, EPA3055DZ:1996, EPA3055EA:1996, EPA3055EB:1996, EPA3055EC:1996, EPA3055ED:1996, EPA3055EE:1996, EPA3055EF:1996, EPA3055EG:1996, EPA3055EH:1996, EPA3055EI:1996, EPA3055EJ:1996, EPA3055EK:1996, EPA3055EL:1996, EPA3055EM:1996, EPA3055EN:1996, EPA3055EO:1996, EPA3055EP:1996, EPA3055EQ:1996, EPA3055ER:1996, EPA3055ES:1996, EPA3055ET:1996, EPA3055EU:1996, EPA3055EV:1996, EPA3055EW:1996, EPA3055EX:1996, EPA3055EY:1996, EPA3055EZ:1996, EPA3055FA:1996, EPA3055FB:1996, EPA3055FC:1996, EPA3055FD:1996, EPA3055FE:1996, EPA3055FF:1996, EPA3055FG:1996, EPA3055FH:1996, EPA3055FI:1996, EPA3055FJ:1996, EPA3055FK:1996, EPA3055FL:1996, EPA3055FM:1996, EPA3055FN:1996, EPA3055FO:1996, EPA3055FP:1996, EPA3055FQ:1996, EPA3055FR:1996, EPA3055FS:1996, EPA3055FT:1996, EPA3055FU:1996, EPA3055FV:1996, EPA3055FW:1996, EPA3055FX:1996, EPA3055FY:1996, EPA3055FZ:1996, EPA3055GA:1996, EPA3055GB:1996, EPA3055GC:1996, EPA3055GD:1996, EPA3055GE:1996, EPA3055GF:1996, EPA3055GG:1996, EPA3055GH:1996, EPA3055GI:1996, EPA3055GJ:1996, EPA3055GK:1996, EPA3055GL:1996, EPA3055GM:1996, EPA3055GN:1996, EPA3055GO:1996, EPA3055GP:1996, EPA3055GQ:1996, EPA3055GR:1996, EPA3055GS:1996, EPA3055GT:1996, EPA3055GU:1996, EPA3055GV:1996, EPA3055GW:1996, EPA3055GX:1996, EPA3055GY:1996, EPA3055GZ:1996, EPA3055HA:1996, EPA3055HB:1996, EPA3055HC:1996, EPA3055HD:1996, EPA3055HE:1996, EPA3055HF:1996, EPA3055HG:1996, EPA3055HH:1996, EPA3055HI:1996, EPA3055HJ:1996, EPA3055HK:1996, EPA3055HL:1996, EPA3055HM:1996, EPA3055HN:1996, EPA3055HO:1996, EPA3055HP:1996, EPA3055HQ:1996, EPA3055HR:1996, EPA3055HS:1996, EPA3055HT:1996, EPA3055HU:1996, EPA3055HV:1996, EPA3055HW:1996, EPA3055HX:1996, EPA3055HY:1996, EPA3055HZ:1996, EPA3055IA:1996, EPA3055IB:1996, EPA3055IC:1996, EPA3055ID:1996, EPA3055IE:1996, EPA3055IF:1996, EPA3055IG:1996, EPA3055IH:1996, EPA3055II:1996, EPA3055IJ:1996, EPA3055IK:1996, EPA3055IL:1996, EPA3055IM:1996, EPA3055IN:1996, EPA3055IO:1996, EPA3055IP:1996, EPA3055IQ:1996, EPA3055IR:1996, EPA3055IS:1996, EPA3055IT:1996, EPA3055IU:1996, EPA3055IV:1996, EPA3055IW:1996, EPA3055IX:1996, EPA3055IY:1996, EPA3055IZ:1996, EPA3055JA:1996, EPA3055JB:1996, EPA3055JC:1996, EPA3055JD:1996, EPA3055JE:1996, EPA3055JF:1996, EPA3055JG:1996, EPA3055JH:1996, EPA3055JI:1996, EPA3055JJ:1996, EPA3055JK:1996, EPA3055JL:1996, EPA3055JM:1996, EPA3055JN:1996, EPA3055JO:1996, EPA3055JP:1996, EPA3055JQ:1996, EPA3055JR:1996, EPA3055JS:1996, EPA3055JT:1996, EPA3055JU:1996, EPA3055JV:1996, EPA3055JW:1996, EPA3055JX:1996, EPA3055JY:1996, EPA3055JZ:1996, EPA3055KA:1996, EPA3055KB:1996, EPA3055KC:1996, EPA3055KD:1996, EPA3055KE:1996, EPA3055KF:1996, EPA3055KG:1996, EPA3055KH:1996, EPA3055KI:1996, EPA3055KJ:1996, EPA3055KL:1996, EPA3055KM:1996, EPA3055KN:1996, EPA3055KO:1996, EPA3055KP:1996, EPA3055KQ:1996, EPA3055KR:1996, EPA3055KS:1996, EPA3055KT:1996, EPA3055KU:1996, EPA3055KV:1996, EPA3055KW:1996, EPA3055KX:1996, EPA3055KY:1996, EPA3055KZ:1996, EPA3055LA:1996, EPA3055LB:1996, EPA3055LC:1996, EPA3055LD:1996, EPA3055LE:1996, EPA3055LF:1996, EPA3055LG:1996, EPA3055LH:1996, EPA3055LI:1996, EPA3055LJ:1996, EPA3055LK:1996, EPA3055LL:1996, EPA3055LM:1996, EPA3055LN:1996, EPA3055LO:1996, EPA3055LP:1996, EPA3055LQ:1996, EPA3055LR:1996, EPA3055LS:1996, EPA3055LT:1996, EPA3055LU:1996, EPA3055LV:1996, EPA3055LW:1996, EPA3055LX:1996, EPA3055LY:1996, EPA3055LZ:1996, EPA3055MA:1996, EPA3055MB:1996, EPA3055MC:1996, EPA3055MD:1996, EPA3055ME:1996, EPA3055MF:1996, EPA3055MG:1996, EPA3055MH:1996, EPA3055MI:1996, EPA3055MJ:1996, EPA3055MK:1996, EPA3055ML:1996, EPA3055MM:1996, EPA3055MN:1996, EPA3055MO:1996, EPA3055MP:1996, EPA3055MQ:1996, EPA3055MR:1996, EPA3055MS:1996, EPA3055MT:1996, EPA3055MU:1996, EPA3055MV:1996, EPA3055MW:1996, EPA3055MX:1996, EPA3055MY:1996, EPA3055MZ:1996, EPA3055NA:1996, EPA3055NB:1996, EPA3055NC:1996, EPA3055ND:1996, EPA3055NE:1996, EPA3055NF:1996, EPA3055NG:1996, EPA3055NH:1996, EPA3055NI:1996, EPA3055NJ:1996, EPA3055NK:1996, EPA3055NL:1996, EPA3055NM:1996, EPA3055NN:1996, EPA3055NO:1996, EPA3055NP:1996, EPA3055NQ:1996, EPA3055NR:1996, EPA3055NS:1996, EPA3055NT:1996, EPA3055NU:1996, EPA3055NV:1996, EPA3055NW:1996, EPA3055NX:1996, EPA3055NY:1996, EPA3055NZ:1996, EPA3055OA:1996, EPA3055OB:1996, EPA3055OC:1996, EPA3055OD:1996, EPA3055OE:1996, EPA3055OF:1996, EPA3055OG:1996, EPA3055OH:1996, EPA3055OI:1996, EPA3055OJ:1996, EPA3055OK:1996, EPA3055OL:1996, EPA3055OM:1996, EPA3055ON:1996, EPA3055OO:1996, EPA3055OP:1996, EPA3055OQ:1996, EPA3055OR:1996, EPA3055OS:1996, EPA3055OT:1996, EPA3055OU:1996, EPA3055OV:1996, EPA3055OW:1996, EPA3055OX:1996, EPA3055OY:1996, EPA3055OZ:1996, EPA3055PA:1996, EPA3055PB:1996, EPA3055PC:1996, EPA3055PD:1996, EPA3055PE:1996, EPA3055PF:1996, EPA3055PG:1996, EPA3055PH:1996, EPA3055PI:1996, EPA3055PJ:1996, EPA3055PK:1996, EPA3055PL:1996, EPA3055PM:1996, EPA3055PN:1996, EPA3055PO:1996, EPA3055PP:1996, EPA3055PQ:1996, EPA3055PR:1996, EPA3055PS:1996, EPA3055PT:1996, EPA3055PU:1996, EPA3055PV:1996, EPA3055PW:1996, EPA3055PX:1996, EPA3055PY:1996, EPA3055PZ:1996, EPA3055QA:1996, EPA3055QB:1996, EPA3055QC:1996, EPA3055QD:1996, EPA3055QE:1996, EPA3055QF:1996, EPA3055QG:1996, EPA3055QH:1996, EPA3055QI:1996, EPA3055QJ:1996, EPA3055QK:1996, EPA3055QL:1996, EPA3055QM:1996, EPA3055QN:1996, EPA3055QO:1996, EPA3055QP:1996, EPA3055QQ:1996, EPA3055QR:1996, EPA3055QS:1996, EPA3055QT:1996, EPA3055QU:1996, EPA3055QV:1996, EPA3055QW:1996, EPA3055QX:1996, EPA3055QY:1996, EPA3055QZ:1996, EPA3055RA:1996, EPA3055RB:1996, EPA3055RC:1996, EPA3055RD:1996, EPA3055RE:1996, EPA3055RF:1996, EPA3055RG:1996, EPA3055RH:1996, EPA3055RI:1996, EPA3055RJ:1996, EPA3055RK:1996, EPA3055RL:1996, EPA3055RM:1996, EPA3055RN:1996, EPA3055RO:1996, EPA3055RP:1996, EPA3055RQ:1996, EPA3055RR:1996, EPA3055RS:1996, EPA3055RT:1996, EPA3055RU:1996, EPA3055RV:1996, EPA3055RW:1996, EPA3055RX:1996, EPA3055RY:1996, EPA3055RZ:1996, EPA3055SA:1996, EPA3055SB:1996, EPA3055SC:1996, EPA3055SD:1996, EPA3055SE:1996, EPA3055SF:1996, EPA3055SG:1996, EPA3055SH:1996, EPA3055SI:1996, EPA3055SJ:1996, EPA3055SK:1996, EPA3055SL:1996, EPA3055SM:1996, EPA3055SN:1996, EPA3055SO:1996, EPA3055SP:1996, EPA3055SQ:1996, EPA3055SR:1996, EPA3055SS:1996, EPA3055ST:1996, EPA3055SU:1996, EPA3055SV:1996, EPA3055SW:1996, EPA3055SX:1996, EPA3055SY:1996, EPA3055SZ:1996, EPA3055TA:1996, EPA3055TB:1996, EPA3055TC:1996, EPA3055TD:1996, EPA3055TE:1996, EPA3055TF:1996, EPA3055TG:1996, EPA3055TH:1996, EPA3055TI:1996, EPA3055TJ:1996, EPA3055TK:1996, EPA3055TL:1996, EPA3055TM:1996, EPA3055TN:1996, EPA3055TO:1996, EPA3055TP:1996, EPA3055TQ:1996, EPA3055TR:1996, EPA3055TS:1996, EPA3055TT:1996, EPA3055TU:1996, EPA3055TV:1996, EPA3055TW:1996, EPA3055TX:1996, EPA3055TY:1996, EPA3055TZ:1996, EPA3055UA:1996, EPA3055UB:1996, EPA3055UC:1996, EPA3055UD:1996, EPA3055UE:1996, EPA3055UF:1996, EPA3055UG:1996, EPA3055UH:1996, EPA3055UI:1996, EPA3055UJ:1996, EPA3055UK:1996, EPA3055UL:1996, EPA3055UM:1996, EPA3055UN:1996, EPA3055UO:1996, EPA3055UP:1996, EPA3055UQ:1996, EPA3055UR:1996, EPA3055US:1996, EPA3055UT:1996, EPA3055UU:1996, EPA3055UV:1996, EPA3055UW:1996, EPA3055UX:1996, EPA3055UY:1996, EPA3055UZ:1996, EPA3055VA:1996, EPA3055VB:1996, EPA3055VC:1996, EPA3055VD:1996, EPA3055VE:1996, EPA3055VF:1996, EPA3055VG:1996, EPA3055VH:1996, EPA3055VI:1996, EPA3055VJ:1996, EPA3055VK:1996, EPA3055VL:1996, EPA3055VM:1996, EPA3055VN:1996, EPA3055VO:1996, EPA3055VP:1996, EPA3055VQ:1996, EPA3055VR:1996, EPA3055VS:1996, EPA3055VT:1996, EPA3055VU:1996, EPA3055VV:1996, EPA3055VW:1996, EPA3055VX:1996, EPA3055VY:1996, EPA3055VZ:1996, EPA3055WA:1996, EPA3055WB:1996, EPA3055WC:1996, EPA3055WD:1996, EPA3055WE:1996



Meilleur Source International Company 12 mois de service de garantie sur votre produit. votre carte de garantie est un document important. vous devrez présenter cette carte de garantie de bénéficier de notre service de garantie.

Conditions & amp; conditions:

Meilleur Source International Company 12 mois de service de garantie sur votre produit. votre carte de garantie est un document important. vous devrez présenter cette carte de garantie de bénéficier de notre service de garantie.

Conditions & amp; conditions:

Conditions & amp; conditions:

b) Au cours de la période de garantie, pour la répartition causé par une mauvaise utilisation ou

d'autres raisons qui sont hors de la portée de la garantie, les utilisateurs peuvent réparer les produits en montrant cette carte. Nous prélèverons pour les composants.
Dans les circonstances suivantes, l'entretien sera facturé:

Photos du produit

Usine



Garantie:

a) libre de la période de maintenance -Charge du produit est de 12 mois. Pendant ce temps, nous pouvons réparer gratuitement (dommages non causés par une mauvaise utilisation ou le vandalisme). Pour la réparation après la période de garantie, des frais d'entretien sera facturée.

c) Lorsque les produits ont besoin d'entretien, se il vous plaît remettre la carte de garantie avec les produits à la fabrication ou le distributeur local.

d) Ouverture de l'intérieur des produits et déchirer l'étiquette d'étanchéité privé est hors de la portée de la garantie.

e) Nous ne avons pas la réparation du produit après qu'il a été modifié ou ajouté d'autres fonctions.

Composants en raison de l'attrition normale 1. contrôle de période, d'entretien ou de changement.

2. Les dommages dus à l'accident, l'extrusion, inondation artificielle, de l'humidité ou d'autres raisons personnelles.

3. Les dommages dus aux inondations, le feu, la foudre et d'autres calamités naturelles ou de force sont spécialisés facteurs d'incidents

4. article réparé par les centres de réparation non autorisés